

Any mask containing metal could cause burns during an MRI, FDA warns

December 8 2020



(HealthDay)—Patients who wear face masks with metal parts or coatings



during MRIs could suffer facial burns, the U.S. Food and Drug Administration warned Monday.

That's because <u>metal parts</u> such as bendable nose clips or wires, staples on the headband, nanoparticles (ultrafine particles), or antimicrobial coating that may contain metal (such as silver or copper) can heat up during an MRI.

The FDA recently received a report about a patient's face being burned by metal in a <u>face mask</u> worn during an MRI.

"Given the increased use of face masks during the COVID-19 pandemic, the FDA wants <u>patients</u> and <u>health care providers</u> to be aware of the potential risk of face burns related to the use of patient face masks containing metal during an MRI," an agency news release stated.

Patients may not be able to tell if their face mask has metal in it, and should ask staff performing the MRI to confirm that the face mask is free of metal, the FDA said.

If the absence of metal cannot be confirmed and a patient needs to wear a face mask during an MRI, an alternative face mask confirmed to be free of metal should be used, the agency advised.

It encouraged health care providers who perform MRI exams to provide face masks without metal to patients having an MRI.

Incidents where patients who are burned by a face mask during an MRI should be reported to the FDA. Doing so could provide information that helps improve <u>patient safety</u>.

MRI uses strong magnets and <u>radio waves</u> to create images of the inside of the body, to diagnose disease or injury and to monitor medical



treatment.

Burns from metal objects worn by patients during an MRI exam are a known issue and all patients should be screened for metallic objects before MRI exams, the agency said.

More information: The American Academy of Family Physicians has more on MRI.

Copyright © 2020 HealthDay. All rights reserved.

Citation: Any mask containing metal could cause burns during an MRI, FDA warns (2020, December 8) retrieved 26 April 2024 from https://medicalxpress.com/news/2020-12-mask-metal-mri-fda.html

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.