


# Inaccurate oximeter readings could limit transplants, heart pumps for Black patients with heart failure study finds

February 21 2024, by Noah Fromson

---



Credit: Unsplash/CC0 Public Domain

Racially biased readings of oxygen levels in the blood using pulse oximeters may further limit opportunities for Black patients with heart

failure to receive potentially lifesaving treatments, such as heart pumps and transplants, a Michigan Medicine study finds.

"This is especially important because we know that Black patients are already less likely to receive [heart pumps](#) or [transplants](#) compared to their white counterparts, and these inaccurate readings can further widen a disparity that must be addressed by our health care system," said first author Scott W. Ketcham, M.D., a third year fellow in cardiovascular medicine at the University of Michigan Health.

During the COVID-19 pandemic, U-M researchers [uncovered](#) that pulse oximeters—devices placed on the finger to detect blood oxygen levels rather than directly from the blood—may not provide accurate readings for Black patients.

Heart failure providers use pulse oximeter readings to guide medication management decisions, as well as to determine whether patients are candidates for heart transplants or left ventricular assist devices, known as LVADs, which assist the heart in pumping.

In a review of adult [heart failure](#) patients treated in U-M Health's medical and surgical cardiac ICUs between 2016 and late 2022, researchers found that [pulse oximeter readings underestimated](#) how much blood was pumping out of a patient's heart and overestimated the resistance in the blood vessels.

The [results](#) are published in *Circulation: Cardiovascular Quality and Outcomes*.

"In addition to possibly precluding Black patients from being candidates for LVADs or heart transplants, these inaccurate measurements could result in the unnecessary use of medications that affect heart and vessel function," said co-author Matthew C. Konerman, M.D., a heart failure

cardiologist at the U-M Health Frankel Cardiovascular Center.

On Feb. 2, 2024, the United States Food and Drug Administration held a [public advisory committee meeting](#) to discuss approaches to improve methods used to evaluate the performance of pulse oximeters with respect to skin pigmentation, race and ethnicity.

As changes are evaluated and considered, the research team says, the results should prompt heart failure providers to rethink their management strategies.

"For our Black patients with heart failure, we need to either measure [oxygen saturation](#) directly from the blood or use other methods to measure hemodynamics if we are using them to guide treatment of these patients," said senior author Sarah K. Adie, PharmD, B.C.C.P., a clinical pharmacy specialist in cardiology at U-M Health and adjunct clinical assistant professor in the U-M College of Pharmacy.

**More information:** Scott W. Ketcham et al, Racial Bias in Pulse Oximetry Measurement: Considerations in Patients With Heart Failure, *Circulation: Cardiovascular Quality and Outcomes* (2024). [DOI: 10.1161/CIRCOUTCOMES.123.010390](#)

Provided by University of Michigan

Citation: Inaccurate oximeter readings could limit transplants, heart pumps for Black patients with heart failure study finds (2024, February 21) retrieved 11 May 2024 from <https://medicalxpress.com/news/2024-02-inaccurate-oximeter-limit-transplants-heart.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.
---